

Hot Work Signs

THE SIGNS OF A SAFE INDUSTRY



See page 102 for more vinyl adhesive signs

ACETYLENE

2.25x9 VPO PD-0046

DO NOT OPERATE WITHOUT EYE PROTECTION

2.25x9 VPO PD-1151

FLAMMABLE

2.25x9 VPO PD-2681

FLAMMABLE KEEP FLAMES AND HEAT AWAY

2.25x9 VPO PD-2686

NO SMOKING NO OPEN FLAMES

2.25x9 VPO PD-4876

NO SMOKING

2.25x9 VPO PD-4856

NO SMOKING, MATCHES OR OPEN LIGHTS

2.25x9 VPO PD-4897

OXYGEN

2.25x9 VPO PD-5727

PROPANE

2.25x9 VPO PD-6038

WEAR PROPER SAFETY EQUIPMENT

2.25x9 VPO PD-9215

SAVE YOUR EYES WEAR EYE PROTECTION

2.25x9 VPO PD-7121

STAND ME UP AND TIE ME UP I CAN BE DANGEROUS

2.25x9 VPO PD-8123

EMPTY CYLINDERS

4x20 AL G4-16641
PL G4-16643
VPO G4-16644

FULL CYLINDERS

4x20 AL G4-27101
PL G4-27103
VPO G4-27104

OXYGEN

4x20 AL G4-57281
PL G4-57283
VPO G4-57284

ACETYLENE

4x20 AL G4-00441
PL G4-00443
VPO G4-00444

NO SMOKING OR OPEN FLAMES

4x20 AL G4-48821
PL G4-48823
VPO G4-48824

NO SMOKING

4x20 AL G4-48571
PL G4-48573
VPO G4-48574

FIRE EXTINGUISHER

4x20 AL G4-26281
PL G4-26283
VPO G4-26284

See page 25 for more 7"x10" Cylinder signs printed on pressure sensitive vinyl

**ACETYLENE
EMPTY
CYLINDERS**

7x10 VPO CL-164

**ACETYLENE
FULL
CYLINDERS**

7x10 VPO CL-234

EMPTY

7x10 VPO CL-184

FULL

7x10 VPO CL-204

**NON-FLAMMABLE
GAS**

7x10 VPO CL-224

**OXYGEN
EMPTY
CYLINDERS**

7x10 VPO CL-124

**OXYGEN
FULL
CYLINDERS**

7x10 VPO CL-284

**CAUTION
HOT**

3x5 VPO C-372314
7x10 AL C-372321
FG C-372322
PL C-372323
VPO C-372324
10x14 AL C-372331
FG C-372332
PL C-372333
VPO C-372334

**CAUTION
HOT
DO NOT TOUCH**

3x5 VPO C-372414
7x10 AL C-372421
FG C-372422
PL C-372423
VPO C-372424
10x14 AL C-372431
FG C-372432
PL C-372433
VPO C-372434

**WARNING
HOT**

3x5 VPO W-990114
7x10 AL W-990121
FG W-990122
PL W-990123
VPO W-990124
10x14 AL W-990131
FG W-990132
PL W-990133
VPO W-990134

**DANGER
HOT
PELIGRO
CALIENTE**

7x10 AL M-001121
FG M-001122
PL M-001123
VPO M-001124
10x14 AL M-001131
FG M-001132
PL M-001133
VPO M-001134

**CAUTION
TOXIC
VAPORS**

3x5 VPO C-812414
7x10 AL C-812421
FG C-812422
PL C-812423
VPO C-812424
10x14 AL C-812431
FG C-812432
PL C-812433
VPO C-812434

**CAUTION
WELDING
AREA**

3x5 VPO C-922214
7x10 AL C-922221
FG C-922222
PL C-922223
VPO C-922224
10x14 AL C-922231
FG C-922232
PL C-922233
VPO C-922234

**DANGER
DO NOT
WATCH THE ARC**

3x5 VPO D-114714
7x10 AL D-114721
FG D-114722
PL D-114723
VPO D-114724
10x14 AL D-114731
FG D-114732
PL D-114733
VPO D-114734

**DANGER
DO NOT WATCH
ARC WELDER AT WORK
THE LIGHT
MAY BLIND YOU**

3x5 VPO D-114614
7x10 AL D-114621
FG D-114622
PL D-114623
VPO D-114624
10x14 AL D-114631
FG D-114632
PL D-114633
VPO D-114634

**DANGER
HOT**

3x5 VPO D-375214
7x10 AL D-375221
FG D-375222
PL D-375223
VPO D-375224
10x14 AL D-375231
FG D-375232
PL D-375233
VPO D-375234

**DANGER
HOT EQUIPMENT
UNAUTHORIZED PERSONS
KEEP OUT**

3x5 VPO D-375314
7x10 AL D-375321
FG D-375322
PL D-375323
VPO D-375324
10x14 AL D-375331
FG D-375332
PL D-375333
VPO D-375334

**DANGER
HOT SURFACE
DO NOT TOUCH**

3x5 VPO D-376114
7x10 AL D-376121
FG D-376122
PL D-376123
VPO D-376124
10x14 AL D-376131
FG D-376132
PL D-376133
VPO D-376134

**DANGER
HOT
SURFACE**

3x5 VPO D-375914
7x10 AL D-375921
FG D-375922
PL D-375923
VPO D-375924
10x14 AL D-375931
FG D-375932
PL D-375933
VPO D-375934

**ACETYLENE
NO SMOKING
OR
OPEN FLAMES**

3x5 VPO G-000514
7x10 AL G-000521
FG G-000522
PL G-000523
VPO G-000524
10x14 AL G-000531
FG G-000532
PL G-000533
VPO G-000534

**EMPTY
CYLINDERS**

3x5 VPO G-166414
7x10 AL G-166421
FG G-166422
PL G-166423
VPO G-166424
10x14 AL G-166431
FG G-166432
PL G-166433
VPO G-166434

**FULL
CYLINDERS**

3x5 VPO G-271014
7x10 AL G-271021
FG G-271022
PL G-271023
VPO G-271024
10x14 AL G-271031
FG G-271032
PL G-271033
VPO G-271034

**EMPTY
CYLINDERS
DO NOT USE**

3x5 VPO G-166514
7x10 AL G-166521
FG G-166522
PL G-166523
VPO G-166524
10x14 AL G-166531
FG G-166532
PL G-166533
VPO G-166534

**FULL
CYLINDERS
READY FOR USE**

3x5 VPO G-271114
7x10 AL G-271121
FG G-271122
PL G-271123
VPO G-271124
10x14 AL G-271131
FG G-271132
PL G-271133
VPO G-271134

**OXYGEN
NO SMOKING
OR
OPEN FLAMES**

3x5 VPO G-573014
7x10 AL G-573021
FG G-573022
PL G-573023
VPO G-573024
10x14 AL G-573031
FG G-573032
PL G-573033
VPO G-573034

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY

